

NOTE: In the event of removing the turntable motor cover this part should be refitted using screw connection: 50282957005 (7-10)